


ARCHITECT




394 SE Highland Park Dr. PO Box 111 College Place. WA 99324 509.525.1250 Kennewick, WA 509.585.0363 Lincoln City, Or 541.764.3960

www.DEKaia.com dekaia@charter.net



Modifications to: City of College Place Municipal Building 625 S. College Ave. College Place WA Map 350736600525

85% CD Review



A2.1.1


SCALE: 1" = 10'

ARCHITECT



394 SE Highland Park Dr. PO Box 111 College Place. WA 99324 509.525.1250 Kennewick, WA 509.585.0363 Lincoln City, Or 541.764.3960

www.DEKaia.com dekaia@charter.net



Modifications to:
City of College Place
Municipal Building
625 S. College Ave.
College Place WA
Map 350736600525

85% CD Review

COMM 1818

FILE 1818bA2.1.1

DRAWN EK

CHECKED DEKaia


DATE Aug '19

PRINTED

SHEET

A2.1.1

OF



DEMOLITION NOTES

- Remove existing Garage Door and associated interior and exterior Trim and Hardware.
- Remove existing Garage Man Door, Frame, Trim and Hardware.
- Remove existing Concrete Garage Floor.
- Remove existing Sally Port Door, Frame, Trim and Hardware in CMU
- 5 Remove Existing Gypsum Board at walls and Ceiling
- Remove existing Holding Cell Door, Frame, Trim and Hardware
- Remove existing Inmate Conference Room Counter, Door, Frame, Trim and Hardware
- 8 Remove existing Inmate Visitor Enclosure with Sidelite, Door, Frame,
- (9) Remove existing inmate Visitor to Conference window
- Remove existing Holding Cell Bunk, including in slab anchors
- Remove existing Holding Cell Plumbing Fixture, including above slab plumbing. Terminate Water Supply and Sewer Lines below existing concrete slab.
- Remove existing Holding Cell concrete ceiling. Provide Temporary Roof Structure Support until permanent new construction can support existing
- Remove existing Holding Cell and Booking exterior CMU and Brick Veneer Bearing Walls. Provide Temporary Roof Structure Support until permanent new construction can support existing Roof.
- Remove all other existing Booking, Sally Port, Inmate Conference and Holding Cell Interior CMU Partitions. Provide Temporary Roof Structure Support until permanent new construction can support existing Roof. Remove and Terminate all utilities to perimeter of Demolition area
- Remove existing Booking double layer Gypsum Ceiling. Maintain existing insulation in present location.
- (16) Remove existing Booking Room Door, Frame, Trim and Hardware
- Remove Existing Security Cameras and associated conduits and cables.


 Owner will retain possession of these items.
- Remove Door Frame and hardware previously used at door 138

ARCHITECT



394 SE Highland Park Dr. PO Box 111
College Place. WA 99324
509.525.1250
Kennewick, WA
509.585.0363
Lincoln City, Or
541.764.3960

www.DEKaia.com dekaia@charter.net



Modifications to: City of College Place Municipal Building 625 S. College Ave. College Place WA Map 350736600525

85% CD Review

COMM 1818

FILE 1818bD2.1.1

DRAWN EK

CHECKED DEKaia

DATE Aug '19

PRINTED

D2.1.1

OF